	Sanitized Copy Approved for Release 2011/04/19 : CIA-RDP8	82-00457R008500600011-4 REPORT 50X1-HUM
	INFORMATION REPORT	CD NO.
		DATE DISTR. 21 SEP 51
COUNTRY	USER (Black Sea)	NO. OF PAGES 1.
SUBJECT	Port of Thapse	NO. OF FAGES 3.
PLACE ACQUIRED		NO. OF ENCLS. 1
ATE OF		SUPPLEMENT TO 50X1-HUM REPORT NO.
THIS DOCUMENTS U.S. C., 28 ANN OF ITS COVIETY HEIGHT DE 12-12-1	CONTACT O HISTOCIANION ASPECTED THE LIGHTOSEA DEPENSE TATES THEND THE SEAMING OF THE SEPICIANS ACT SO RE, AS IN HERE, TO FEARINGS OF THE SEPICIANS ACT SO RE, AS IN HERE, TO FEARINGS OF THE SEVENTION OF THE SEPECIAL TO SET OF THE SERVE SERVER	ALUATED INFORMATION  NOT CIRCULATE 50X1-HUM
1.	water supply at this port and the water system is w	there is an excellent
2.	sent from Thapse to Novorossiisk.  There were no signs of any antiaircraft defenses or	fortifications of any
~ -	kind in the port itself or the surrounding area. Mesen; however, very few soldiers were seen.	any Soviet sailors were
3.	a number of Soviet vessels in the port b	50X1-HUM 50X1-HUM
<b>4</b> •	No foreign ships, other than those under the Ful to enter the port. Therefore, there is no Inflet Bulgarian vessel errives at the port a representati agency at Novorossiisk to make the mecessary arrang necessary formalities.	agency; however, when a
	Attachments: Sketch of the port of Tuapse.	
	•	******
		. *
	CONFIDENTIAL	
STATE	CLASSIFICATION CONTROL - US OFFICE NAVY NRRB DISTRIBUTION	als ONLY
ARMY	AIR FBI	
	No Cha ☐ Dsc	classified Changed To: TS S 50X1-HUM  The To-2 24
	Sanitized Copy Approved for Release 2011/04/19 : CIA-RDP8	82-00457R008500600011-4

50X1-HUM

Chilliant Infalligence addads

## Key to the Sketch of the Port of Tuapse

- The breakwater has been partially destroyed and has not as yet been repaired. No activity was seen on the breakwater.
- 2. The quay is being extended by approximately 1:00 meters. This is being done with reinforced concrete pylons and cement floorings. The work was not completed at the time of observation.
- Two cranes of five tons each.
- 4. Large cement store for work being done on the quay.
- 5. The quay is damaged but is now undergoing repairs. At the moment it is dangerous to come alongside and there are constant accidents.
- 6. This part of the wharf is being rebuilt but it is not completed as yet.
- 7. Repair shop for merchant ships. This shop has been largely rebuilt and at the time of this report the 5,000-ton Soviet cargo steamer <u>Stary Bolsnevik</u> was being overhauled.
- 8. Anchored at this spot was a large submarine chaser and many patrol boats.
- 9. The oil wharf was in good condition. Alongside the wharf was the 10,000-ton Soviet tanker Mcskva. There is deep water alongside this wharf capable of taking ships up to 10,000 tons.
- 10. Breakwater constructed of huge stone blocks.
- 11. Large light which is visible at a distance of 15 miles. This point is known as kodoshe.
- 12. Buoy with a light.
- 13. Two lights. To enter the port shipping must navigate along the line between No. 12 and these two lights.
- 14: Two entrance lights red and green.

15.	Depth of	the water	alongside	the quay is	22-25	l'eet.	50)	K1-HUN

- 16. later depth is 25 feet here.
- 17. Anchored at this point was the l,000 ton Soviet cargo vessel Orao.

CONFIDENTIAL

Tadifact - US Officials only

50X1-HUM

CANTRAL INTELLIGENCE AGLICY

Attachment

Sketch of the Port of Tuapse

